

1. Product and company identification

- **Product name:** Hologram Glitter Spray Glitter spray aerosol silk matt 400ml
- **Manufacturer/Importer:** European Aerosols GmbH
- **Address:** DE 69115 Heidelberg , Häusserstraße 36
- **Contact:** info@montana-cans.com

2. Description of the product

- **Intended use:** Special sprays for decoration, floristry and creative applications.
- **Material composition:**
 - **Ingredients:** Acetone, n-butyl acetate, 2-methoxy-1-methylethyl acetate, propane, butane, isobutane, ethanol, 2-propanol, titanium dioxide, xylene.

3. Hazard warnings

- **H222:** Danger. Extremely flammable aerosol.
- **H229:** Pressurized container: May burst if heated.
- **H319:** Causes serious eye irritation.
- **H336:** May cause drowsiness or dizziness.
- **EUH066:** Repeated exposure may cause skin dryness or cracking.
- **EUH211:** Warning! Spraying may produce hazardous respirable droplets. Do not breathe aerosol or mist.

4. Precautions

4.1 General precautions

- **P101:** If medical advice is needed, have product container or label at hand.
- **P102:** Keep out of reach of children.

4.2 Handling and use

- **P210:** Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking.
- **P211:** Do not spray on an open flame or other ignition source.
- **P251:** Do not pierce or burn, even after use.
- **P260:** Do not breathe spray.
- **EUH211:** Ensure adequate ventilation when spraying.

4.3 Storage

- **P410+P412:** Protect from sunlight. Do not expose to temperatures exceeding 50 °C.

5. First aid measures

- **If skin contact occurs:** Wash thoroughly with soap and water. Avoid repeated contact.
- **In case of eye contact:** Rinse immediately with plenty of clean water and seek medical advice.
- **If inhaled:** Remove affected person to fresh air. If drowsiness or dizziness occurs, seek medical attention.
- **If swallowed:** Get medical advice immediately. Do not induce vomiting.

6. Firefighting measures

- **Suitable extinguishing agents:** CO₂, foam, powder.
- **Special measures:** Move containers out of danger zone if this can be done without risk. Wear respiratory protection.
- **Note:** Sprays may burst when heated and form explosive mixtures.

7. Storage and transport

- **Storage:**
 - Store in a cool, dry and well-ventilated place.
 - Always keep containers tightly closed.
- **Transport:**
 - Protect from mechanical damage.
 - Do not expose to temperatures above 50 °C.

8. Disposal instructions

- Dispose of contents/container in accordance with local regulations.
- Do not release containers or residual contents into the environment.

9. Additional information

- **Without adequate ventilation:** formation of explosive mixtures possible.
- For further details on safe use, please refer to the instructions on the product packaging.
- Questions? Contact us at info@montana-cans.com.